

List of CATIA keyboard shortcuts

<i>Use this keyboard key (or combination)...</i>	<i>To...</i>
<i>Escape</i>	<i>Exit the current dialog box (when there is one)</i>
<i>F1</i>	<i>Get contextual online help</i>
<i>Shift + F1</i>	<i>Get help on toolbar icons</i>
<i>Shift + F2</i>	<i>Toggle the specification tree overview on and off</i>
<i>F3</i>	<i>Toggle specification tree display on and off</i>
<i>Alt + F8</i>	<i>Run macros</i>
<i>Shift + F3</i>	<i>Activate the graph if the model is active and inversely</i>
<i>Home</i>	<i>Display the top of the graph</i>
<i>End</i>	<i>Display the bottom of the graph</i>
<i>Page Up</i>	<i>Relocate the graph one page up</i>
<i>Page Down</i>	<i>Relocate the graph one page down</i>
<i>Ctrl + Page Up</i>	<i>Zoom In the graph</i>
<i>Ctrl + Page Down</i>	<i>Zoom Out the graph</i>
<i>Up arrow</i>	<i>Relocate the graph 1/10th (one tenth) of a page to the top</i>
<i>Down arrow</i>	<i>Relocate the graph 1/10th (one tenth) of a page to the bottom</i>
<i>Left arrow</i>	<i>Relocate the graph 1/10th (one tenth) of a page to the left</i>
<i>Right arrow</i>	<i>Relocate the graph 1/10th (one tenth) of a page to the right</i>
<i>Ctrl + Tab</i>	<i>Swap active document windows</i>
<i>Alt + Enter</i>	<i>Run the Properties... command</i>
<i>Ctrl + C</i>	<i>Run the Copy command</i>
<i>Ctrl + F</i>	<i>Run the Search... command</i>
<i>Ctrl + G</i>	<i>Run the Selection Sets... command</i>
<i>Ctrl + N</i>	<i>Run the New... command</i>
<i>Ctrl + O</i>	<i>Run the Open... command</i>
<i>Ctrl + P</i>	<i>Run the Print... command</i>
<i>Ctrl + S</i>	<i>Run the Save... command</i>
<i>Ctrl + V</i>	<i>Run the Paste command</i>
<i>Ctrl + X</i>	<i>Run the Cut command</i>
<i>Ctrl + Y</i>	<i>Run the Redo command</i>
<i>Ctrl + Z</i>	<i>Run the Undo command</i>